

Skoda Yeti 2.0 TDI 143HP

1. Box type: VT301200.
2. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

